



0 5 10 MI


LYNDON B. JOHNSON CIVILIAN CONSERVATION CENTER FRANKLIN, NORTH CAROLINA









SECOND FLOOR VACANT





FIRST FLOOR VACANT

BUILDING 10

















FIRST FLOOR

BUILDING 12












SECOND FLOOR





FIRST FLOOR

BUILDING 14











SECOND FLOOR





FIRST FLOOR

JACKSON 4
BUILDING 16










SECOND FLOOR VACANT



FIRST FLOOR VACANT


JACKSON 5


BUILDING 18





LYNDON B. JOHNSON CIVILIAN
CONSERVATION CENTER
FRANKLIN, NORTH CAROLINA


0 10' 20' 40'











Multiple Buildings Fire Alarms



Existing Panels in Bldg#62 Duty Office



Existing Panels in Bldg#62 Duty Office



Typical Existing Horn Strobe Device



Typical Existing Pull Station

Multiple Buildings Fire Alarms



Existing System, Bldg#62 Duty Office