

PERFORMANCE WORK STATEMENT (PWS) [TEMPLATE]

ACCIDENT/BODY REPAIR FOR MCI COACH BUS

PART 1

General Information

1. **GENERAL:** This is a non-personnel services contract to provide complete repair of the body damage on the provided Motor Coach Industries bus. The Government shall not exercise any supervision or control over the contract service providers performing the services herein. Such contract service providers shall be accountable solely to the Contractor who, in turn is responsible to the Government.

1.1 Description of Services/Introduction: The contractor shall provide all personnel, equipment, supplies, facilities, transportation, tools, materials, supervision, and other items and non-personal services necessary to perform complete repair of the body damage on the provided Motor Coach Industries bus as defined in this Performance Work Statement. The contractor shall perform to the standards in this contract.

1.2 Objectives: All parts must be replaced in accordance with Air Force technical order 36-1-191 1.5.1.2 which states any parts replaced must meet or exceed original equipment manufacturer specifications.

1.3 Scope: Perform complete repair of the body damage on the provided Motor Coach Industries bus. *Services include* repairing fan door panel and hinge, door rub rail, door handle, access door, rear panel under taillight, letter board panel, and bumper corner. Services also include replacing right rear access door, fab panel behind rear wheel, wheel well fender, all fender brackets, def panel, rub rail for def panel, left side Air Force decals, 20 lug nut covers. The contractor shall accomplish the replacement of any parts with original equipment manufacturer specifications.

1.4 Period of Performance: The period of performance shall not exceed 90 days.

1.5 Type of Contract: The government will award a (Type of contract to be determined by CCE and the customer).

1.6 Special Qualifications: The contractor must be ASE, I-car and Gold Class certified.

PART 2

DEFINITIONS & ACRONYMS

2. DEFINITIONS AND ACRONYMS:

2.1. DEFINITIONS:

2.1.1. **CONTRACTOR.** A supplier or vendor awarded a contract to provide specific supplies or service to the government. The term used in this contract refers to the prime.

2.1.2. **CONTRACTING OFFICER.** A person with authority to enter into, administer, and or terminate contracts, and make related determinations and findings on behalf of the government. Note: The only individual who can legally bind the government.

2.1.3. **DEFECTIVE SERVICE.** A service output that does not meet the standard of performance associated with the Performance Work Statement.

2.1.4. **KEY PERSONNEL.** Contractor personnel that are evaluated in a source selection process and that may be required to be used in the performance of a contract by the Key Personnel listed in the PWS. When key personnel are used as an evaluation factor in best value procurement, an offer can be rejected if it does not have a firm commitment from the persons that are listed in the proposal.

2.1.5. QUALITY CONTROL. All necessary measures taken by the Contractor to assure that the quality of an end product or service shall meet contract requirements.

2.1.6. SUBCONTRACTOR. One that enters into a contract with a prime contractor. The Government does not have privity of contract with the subcontractor.

PART 3 CONTRACTOR FURNISHED ITEMS AND SERVICES

3. CONTRACTOR FURNISHED ITEMS AND RESPONSIBILITIES:

3.1 General: The Contractor shall furnish all supplies, equipment, facilities and services required to perform work under this contract.

3.2. Materials. The Contractor shall provide all required materials to include hardware, tape, tools and paint.

PART 4 SPECIFIC TASKS

4. Specific Tasks:

4.1. Basic Services. The contractor shall provide services for repairing the bus back to its original factory body condition.

PART 5
ATTACHMENT/TECHNICAL EXHIBIT LISTING

5. Attachment/Technical Exhibit List:

5.1. Attachment 1– Performance Required/ Bid Sheet

ATTACHMENT 1: Performance Required/ Bid Sheet

Customer Information

Andrews Air Force Base
 Name:
 Address:
 Phone:

Vehicle Information

Vehicle: 2012 Blue MCI D4505
 Style: Coach
 License: AF12B00912
 VIN: 1M86DMUA5CP012683
 Mileage:

#	Operation	Description	Type	Price	Labor	Paint
1						
2		NOTE: This estimate is subject to teardown & parts				
3		verification & final pricing				
4						
5	Repair	Middle body rail on Passenger side	BL			
6	Refinish	Middle body rail on Passenger side	RL			
7						
8	Remove/Install	Passenger side Middle body rail	BL			
9						
10	Repair	Passenger side Door No.1	BL			
11	Refinish	Passenger side Door No.1	RL			
12						
13	Repair	Passenger side door No.2	BL			
14	Refinish	Passenger side door No.2	RL			
15						
16	Repair	Door No.2 decals (two High voltage)	BL			
17		** See decal Package				
18						
19	Remove/Install	Yellow marker light on door No.2	BL			
20						
21	Repair	Center Pillar between door No.2 and No.3	BL			
22	Refinish	Center Pillar between door No.2 and No.3	RL			
23						

Estimate

Customer Information

Name: Andrews Air Force Base
Address:
Phone:

Vehicle Information

Vehicle: 2012 Blue MCI D4505
Style: Coach
License: AF12B00912
VIN: 1M86DMUA5CP012683
Mileage:

24 Repair	Diesel Fuel Only decal on Door No.3	BL
25	** See decal Package	
26		
27 Repair	Passenger Door No.3	BL
28 Refinish	Passenger Door No.3	RL
29		
30 Repair	Center pillar between door No.3 and No.4	BL
31 Refinish	Center pillar between door No.3 and No.4	RL
32		
33 Repair	Replace Middle molding on center pilar between 3&4	BL
34 Remove/Replace	[LineItemData."DESC"]	NW
35		
36 Repair	Passenger door No.4	BL
37 Refinish	Passenger door No.4	RL
38		
39 Repair	Center pilar between Door No.4 and No.5	BL
40 Refinish	Center pilar between Door No.4 and No.5	RL
41		
42 Repair	Adjust and align Battery switch small door	BL
43		
44 Repair	Battery switch decals on Door No4	BL
45	** See decal Package	
46		

Estimate

Customer Information

Name: Andrews Air Force Base
Address:
Phone:

Vehicle Information

Vehicle: 2012 Blue MCI D4505
Style: Coach
License: AF12B00912
VIN: 1M86DMUA5CP012683
Mileage: tbd

47 Repair	Replace Complete Passenger side door No.5	BL
48 Remove/Replace	Complete Passenger Door Assembly #5	NW
49		
50 Refinish	Refinish Complete Passenger side door No.5	
51		
52 Repair	Decals on Door No.5 (four high voltage)	
53 Remove/Replace	** See decal Package	NW
54		
55 Repair	Replace Lower Molding on door No.5	BL
56 Remove/Replace	Lower Molding - Door #5	NW
57		
58 Refinish	Refinish Lower Molding on door No.5	RL
59		
60 Repair	Replace Panel No.1 Next to wheel opening	BL
61 Remove/Replace	Panel No. 1 next to wheel opening (P/S)	NW
62		
63 Refinish	Refinish Panel No.1 Next to wheel opening (P/S)	RL
64		
65 Remove/Install	Access door on DEF Compartment	BL
66		
67 Repair	Lower molding on Panel Next to wheel opening	BL
68 Remove/Replace	Lower Molding on panel next to	NW

Estimate

Customer Information

Name: Andrews Air Force Base
Address:
Phone:

Vehicle Information

Vehicle: 2012 Blue MCI D4505
Style: Coach
License: AF12B00912
VIN: 1M86DMUA5CP012683
Mileage: tbd

	wheel opening	
69		
70 Refinish	Refinish Lower Molding	RL
71		
72 Repair	Replace Passenger side rear Fender (wheel opening)	BL
73 Remove/Replace	Wheel Opening Bracket	NW
73 Remove/Replace	Passenger side rear Fender (wheel opening)	NW
74		
75 Refinish	Refinish Passenger side rear Fender(wheel opening)	RL
76		
77 Repair	Repair & Replace wiring for wheel opening fender	BL
78		
79 Remove/Replace	Wiring harness or repair kit	NW
81		
82 Repair	Replace Rubber Seal & Light - wheel opening	BL
83 Remove/Replace	Wheel Opening rubber gasket	NW
84 Remove/Replace	Lamp Assy, LED Amber	NW
85		
86 Repair	Straighten Inner structure on P/S wheel opening	BL
87 Refinish	Refinish Inner structure on P/S wheel opening	RL
88		
89 Repair	Panel No.2 next to wheel opening on P/S	BL
90 Remove/Replace	Panel No. 2 next to wheel opening on P/S	NW

Estimate

Customer Information

Name: Andrews Air Force Base
Address:
Phone:

Vehicle Information

Vehicle: 2012 Blue MCI D4505
Style: Coach
License: AF12B00912
VIN: 1M86DMUA5CP012683
Mileage:

91		
92 Refinish	Refinish Panel No.2 next to wheel opening on P/S	RL
93		
94 Repair	Replace Baggage Door No.6 (complete)	BL
95 Remove/Replace	Baggage Door No. 6	NW
96		
97 Refinish	Refinish Complete Door No.6	RL
98		
99 Repair	Repair Panel above Passenger side door No.6	
100 Refinish	Panel above Passenger side door No.6	
101		
102 Repair	Replace Pilar between Door No5 and Rear Corner	BL
103 Remove/Replace	Pilar between Door No5 and Rear Corner	
104		
105 Refinish	Refinish Pilar between Door No5 and Rear Corner	
106		
107		
108 Repair	Replace Rear passenger lower corner panel	BL
109 Remove/Replace	Rear passenger lower corner panel	NW
110		
111 Refinish	Refinish Rear passenger lower corner panel	
112		

Estimate

Customer Information

Andrews Air Force Base
Name:
Address:
Phone:

Vehicle Information

Vehicle: 2012 Blue MCI D4505
Style: Coach
License: AF12B00912
VIN: 1M86DMUA5CP012683
Mileage:

113 Repair	Replace Passenger rear corner lower molding	BL
114 Remove/Replace	Passenger rear corner lower molding	NW
115		
116 Refinish	Refinish Passenger rear corner lower molding	RL
117		
118 Remove/Install	Rear lights on rear corner panel	BL
119		
120 Remove/Install	Rear Bumper	BL
121		
122 Repair	Replace Rear bumper module (RH)	BL
122 Repair	Replace Rear bumper filler `	BL
123 Remove/Replace	Rear Bumper Filler - Closing panel	NW
123 Remove/Replace	Module - bumper RH	NW
123		
124		
125 Refinish	Refinish Rear bumper driver and passenger side	RL
126		
127 Repair	Repair Rear bumper driver and passenger side	BL
128		
129 Remove/Install	Driver side rear ligths on upper and low	BL
130		
131 Repair	Repair Driver side rear lower corner panel	BL
132 Refinish	Refinish Driver side rear lower corner panel	RL

Estimate

Customer Information

Andrews Air Force Base
Name:
Address:
Phone:

Vehicle Information

Vehicle: 2012 Blue MCI D4505
Style: Coach
License: AF12B00912
VIN: 1M86DMUA5CP012683
Mileage:

133		
134 Refinish	Refinish Driver side rear upper corner panel	BL
135		
136 Repair	Repair Driver side rear upper corner panel	BL
137		
138 Remove/Install	Driver side rear upper corner panel black	BL
139		
140 Repair	Repair Driver side pillar between door No.5 and	BL
141 Refinish	Refinish Driver side pillar between door No.5 and	RL
142		
143 Repair	Repair Driver side door No.5	BL
144 Refinish	Refinish Driver side door No.5	RL
145		
146 Remove/Install	Reflector on driver side door No.5	BL
147		
148 Repair	Repair Driver side middle body rail	BL
149 Refinish	Refinish Driver side middle body rail	RL
150		
151 Repair	Repair Driver side wheel opening fender	BL
152 Refinish	Refinish Driver side wheel opening fender	RL
153		
154 Remove/Install	Driver side Light on wheel opening fender	BL

Estimate

Customer Information

Andrews Air Force Base
Name:
Address:
Phone:

Vehicle Information

Vehicle: 2012 Blue MCI D4505
Style: Coach
License: AF12B00912
VIN: 1M86DMUA5CP012683
Mileage:

155		
156 Repair	Repair Drivers side lower molding on wheel open	BL
157 Refinish	Refinish Drivers side lower molding on wheel open	RL
158		
159 Repair	Replace Driver side hinge on door No.4	BL
160 Remove/Replace	Driver side hinge on door No.4	NW
161		
162 Repair	Repair Driver side door No.4 (a/c units access)	BL
163 Refinish	Refinish Driver side door No.4 (a/c units access)	RL
164		
165 Repair	Remove Decals on driver side door No.4	BL
166 Remove/Replace	(3) Decals - See Decal Package	NW
167		
168 Remove/Install	Reflector on driver side door No4	BL
169		
170 Repair	Repair Driver side door No.3 Lower damage	BL
171 Refinish	Refinish Driver side door No.3 Lower damage	RL
172		
173 Repair	Repair Driver side middle panel	BL
174 Refinish	Refinish Driver side middle panel	RL
175		
176 Repair	Replace Passenger side rear tire	ML
177 Remove/Replace	Balance	13

Estimate

Customer Information

Andrews Air Force Base
 Name:
 Address:
 Phone:

Vehicle Information

Vehicle: 2012 Blue MCI D4505
 Style: Coach
 License: AF12B00912
 VIN: 1M86DMUA5CP012683
 Mileage:

178 Remove/Replace	Passenger rear Tire	NW
179 Remove/Replace	Wheel Nuts	NW
180 Remove/Replace	Wheel Nut Covers	NW
181		
182 Repair	Inspect Two Rear axles for any damage	ML
183		
184 Repair	Repair Black Middle rail under side windows	BL
185 Refinish	Black Middle rail under side windows	RL
186		
187 Refinish	Deduction for Overlap	RL
188		
189 Remove/Replace	Black Rubber Extrusion - cut to length (24FT)	NW
190	Paint Materials	PM
191	Shop Supplies	SS
192		
193		
194		
195		
196 Remove/Replace	Logo & decals (U.S.AIR FORCE integrity, service,)	NW
197		
198 Remove/Replace	Decal Package - warning labels, lettering, etc	NW
199		
200		
201		

Estimate

Customer Information	Vehicle Information
Andrews Air Force Base	Vehicle: 2012 Blue MCI D4505
Name:	Style: Coach
Address:	License: AF12B00912
	VIN: 1M86DMUA5CP012683
Phone:	Mileage:

202	B
203	B
204	B
205	B
206	B
207	B
208	B
209	B

Totals:	Units:	Rate:	Total:
Estimate/Repair Order Totals			
Parts - New			
PARTS TOTAL			
Body Labor			
Refinish Labor			
Mechanical Labor			
Frame Labor			
Electrical Labor			
LABOR TOTAL			
Shop Supplies			
Paint Materials			
Towing			
Miscellaneous			
Stock Inventory Sales			

Sub Total			
TAX EXEMPT			
GRAND TOTAL			

Estimate

Customer Information

Vehicle Information